

DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street
Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

SURVEY NUMBER: CARR- 1141

NEGATIVE FILE NUMBER:

UTM REFERENCES:
Zone/Easting/NorthingU.S.G.S. QUAD. MAP: Manchester

PRESENT FORMAL NAME:

ORIGINAL FORMAL NAME:

PRESENT USE: Business officesORIGINAL USE: Residence

ARCHITECT/ENGINEER:

BUILDER/CONTRACTOR:

PHYSICAL CONDITION OF STRUCTURE:

Excellent () Good ()
Fair (X) Poor ()

THEME:

STYLE:

DATE BUILT: late 19th c.COUNTY: CARROLLTOWN: MelroseLOCATION: 4219 HANOVER PIKE (MD 30)

COMMON NAME:

FUNCTIONAL TYPE: ResidenceOWNER: Masonry Contractors, IncADDRESS: 4219 Hanover Pike
Manchester Md 21102 374-4144

ACCESSIBILITY TO PUBLIC:

Yes () No (X) Restricted ()

LEVEL OF SIGNIFICANCE:

Local () State () National ()

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone (X) Brick () Concrete () Concrete Block ()
 2. Wall Structure
 - A. Wood: Log () Post and Beam () Balloon ()
 - B. Wood Bearing Masonry: Brick (X) Stone () Concrete () Concrete Block ()
 - C. Iron () D. Steel () E. Other
 3. Wall Covering: Weatherboard () German Siding () Board and Batten ()
Wood Shingle () Shiplap () Novelty () Stucco () Sheet Metal ()
Aluminum () Asphalt Shingle () Brick Veneer () Stone Veneer ()
Bonding Pattern: stretch Other:
 4. Roof Structure
 - A. Truss: Wood (X) Iron () Steel () Concrete ()
 - B. Other:
 5. Roof Covering: Slate () Wood Shingle () Asphalt Shingle (X) Sheet Metal ()
Built Up () Rolled () Tile () Other:
 6. Engineering Structure:
 7. Other:
- Appendages: Porches () Towers () Cupolas () Dormers () Chimneys () Sheds ()
Ells (X) Wings () Other:
- Roof Style: Gable (X) Hip () Shed () Flat () Mansard () Gambrel () Jerkinhead ()
Saw Tooth () With Monitor () With Bellcast () With Parapet ()
With False Front () Other:

Number of Stories: 2Number of Bays: 3 x 1

Approximate Dimensions:

Entrance Location: none

THREAT TO STRUCTURE:

No Threat () Zoning () Roads ()
Development () Deterioration ()
Alteration () Other:

LOCAL ATTITUDES:

Positive () Negative ()
Mixed () Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Unfortunately, the renovation of this house ignored the basic principles of historic preservation - bldg has been sand blasted; replacement window do not reflect historic character of the bldg; main facade has been significantly altered.

RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

non-contributing bldg

REFERENCES:

1862 Martenet's Map:

1877 LG & S Atlas:

SURROUNDING ENVIRONMENT:

Open Lane () Woodland () Scattered Buildings ()
 Moderately Built Up (X) Densely-Built Up ()
 Residential () Commercial ()
 Agricultural () Industrial ()
 Roadside Strip Development ()
 Other:

RECORDED BY:


Joe Getty

ORGANIZATION:

C. L. Dept. of Planning

DATE RECORDED:

7/85



MANCHESTER, MD-PA.

QUADRANGLE

7.5 minute series



1. CARR-1141
2. Carroll County, Maryland
3. Joe Getty
4. July 1985
5. Maryland Historical Trust, Annapolis, Md.
6. West elevation (camera facing east)
7. 1/1